

ADDENDUM NO. 1

The following requests for information were submitted by prospective bidders.

1. Question: After the City has isolated the 12-inch piping from both the water main and the tanks, who is responsible for draining said piping?

Answer: The City will be responsible for draining the 12-inch piping prior to the start of work.

2. Question: What is the intent of the note “Do not locate valves below north balcony” on Sheet LS-32-02; Drawing #3 Piping Plan-Basement?

Answer: Since a valve that is located underneath the north balcony will be difficult to access and operate, neither the north isolation valve nor the motorized isolation valve shall be located below the north balcony. A pipe spool will need to be inserted between the existing pipe stub and the new north isolation valve. The north isolation valve is not shown in the correct location on the drawing.

END OF ADDENDUM NO. 1